



Front (south) elevation. Substantial mortar deterioration is evident. We would rake back mulch and dig dirt as necessary to expose 8 full courses of brick, fully re-point all mortar joints, and replace mulch and dirt after curing has occurred.




Front (south) elevation. Substantial mortar deterioration is evident.



Previous poor repair-wrong color and not an appropriate mortar. Mortar on this elevation is failing




East elevation exhibits substantial mortar deterioration. Recommend fully re-pointing this side.



East elevation exhibits substantial mortar deterioration. Recommend fully re-pointing this side.



East elevation exhibits substantial mortar deterioration. Recommend fully re-pointing this side, including the back (north elevation only to where it meets the original concrete steps.



Northwest corner of home example of empty joints that would be



Northwest corner of home empty joints, would be spot pointed.




Spot point empty and deteriorated joints under deck.



Southwest corner, from corner to chimney, joints exhibit a good deal of deterioration, re-point completely.



West side of house to the north of chimney. Example of joints that would be spot pointed.



Southwest corner, from corner to chimney, joints exhibit a good deal of deterioration, re-point completely.

